



ФРИТЮРНИЦА ЭЛЕКТРИЧЕСКАЯ 700 СЕРИИ TATRA TEF.47

1	HANDLE	Y.EMP.7FE010.001	
2	LID	Y.EMP.7FE010.002	
3	BASKET HANGER SHEETMETAL	Y.EMP.7FE010.003	
4	RESISTANCE	Y.EMP.7FE010.004	
5	BASKET	Y.EMP.7FE010.005	
6	BASKET BOTTOM SHEETMETAL	Y.EMP.7FE010.006	
7	RESISTANCE CONNECTION MIDDLE TOP SHEETMETAL	Y.EMP.7FE010.007	
8	CONTACTOR MTF41	Y.EMP.7FE010.008	
9	BASE FRAME	Y.EMP.7FE010.009	
10	VALVE HANDLE	Y.EMP.7FE010.010	
11	WARNING LAMP	Y.EMP.7FE010.011	
12	YELLOW HINGE RING	Y.EMP.7FE010.012	
13	BUTTON	Y.EMP.7FE010.013	
14	EVACUATION HOSE	Y.EMP.7FE010.014	
15	VALVE	Y.EMP.7FE010.015	
16	SWITCH	Y.EMP.7FE010.016	
17	CHROME HINGE RING	Y.EMP.7FE010.017	
18	LOCK SPRING	Y.EMP.7FE010.018	
19	RESISTANCE CONNECTION SHEETMETAL-RIGHT	Y.EMP.7FE010.019	
20	LOCK CONNECTION YELLOW NUT	Y.EMP.7FE010.020	
21	FEET	Y.EMP.7FE010.021	
22	THERMOSTAT 135-180	Y.EMP.7FE010.022	
23	LOCK HANDLE	Y.EMP.7FE010.023	
24	BUTTON BUFFER	Y.EMP.7FE010.024	
25	THERMO PART CONNECTION SHEETMETAL	Y.EMP.7FE010.025	
26	RESISTANCE SUPPORT SHEETMETAL	Y.EMP.7FE010.026	
27	HINGE LOCK- INNER	Y.EMP.7FE010.027	
28	HINGE LOCK- OUTER	Y.EMP.7FE010.028	
29	RESISTANCE CONNECTION SHEETMETAL-LEFT	Y.EMP.7FE010.029	
30	RESISTANCE CONNECTION MIDDLE BOTTOM SHEETMETAL	Y.EMP.7FE010.030	